

Release Note

1. To reduce the possibility of blue screen when using modem thru PL2303 adapter to connect and disconnect ISP for several times
2. After COM port is closed, driver will ignore the unnecessary interrupt requirement from H/W, so the IRP counter will keep the value.